

Property Inspection Report

Inspector Name: RICK RAPP III

Date Inspected: 20 OCT. 08
 Property Address: 555 Integrity Way
 Owner Name: John Doe
 Property Manager: Michael DePaola
 Damage Noted: No

Owner E-Mail: JDoe@aol.com
 Overall Condition: Good
 Filter Changed: Yes
 Tablet Installed: Yes

Description
 FILTER 20" X 16" AHU HALL


1
2
3
4
5

Property Pictures

Bedroom



HALL



Bedroom



Bedroom




Bedroom




Kitchen



Bath



Bath



Dining room



AHU



LAUNDRY ROOM



Damage Pic (If Applicable)

